



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

September 1, 2010

Reviewed: 

Mine Name: Soma Quarry	Permit Number: S0230065
Operator Name: Nephi Sandstone Corp.	Inspection Date: August 31, 2010
Inspector(s): Wayne H. Western, Ivan Djambov legislature auditor, Jill Marriott accounting department	Time: 9:20 -9:40 AM
Other Participants: None	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The purpose of the inspection was to determine if the overhang had been removed.

Directions to Site:

The site is located east of Leamington, Utah on the south bank of the Sevier River. Approximately 2.3 miles northeast of the cement plant, 39° 35' 08.66" N 112°09' 54.96"

Inspection Summary:

On July 14, 2009, the Division conducted a routine inspection and Division staff noticed that there were overhangs on the highwalls. The Division notified the Operator of the overhangs on the highwall. On November 5, 2009, the Division inspected the site. The Operator had removed some but not all of the overhangs. On April 27, 2010, the Division conducted a follow up inspection and noticed that there are still overhangs on the highwall. On August 31, 2010, the Division visited the site and determined that the overhangs were still present although the Permittee had placed some backfill against the highwall. The Division will proceed by writing a cessation order.

Conclusions and Recommendations:


Inspection Date August 31, 2010

Page 2 of 4

S/023/0065

The Operator failed to eliminate all of the overhangs on the highwall. The Division will issue a cessation order that will require the Operator to eliminate all of the highwalls

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wapiti de la Cruz", written over a horizontal line.

WHW


cc: (OPERATOR)

Jerry_Mansfield@BLM.gov


MSHA

O:\M023-Juab\S0230065-Soma\inspections\insp08312010.doc

S/023/0065



July 14, 2009




April 27, 2010

S/023/0065



August 31, 2010



August 31, 2010